

*READ THIS FIRST – if you have purchased XGate, ignore these instructions and use the XGate CD to install the adapter and drivers– insert the XGate CD into your computer and follow the instructions BEFORE inserting the adapter into your computer*

Installation instructions for USB to Serial Adapter.

- 1) Insert CD ROM in CD drive (or copy to a folder on your hard drive)
- 2) Connect USB to serial adapter to computer
- 3) Windows will then display New Hardware Wizard
- 4) Tell it not to connect to the Internet this time to look for drivers, NEXT
- 5) Tell it to install from a list or a specific location, NEXT
- 6) Select Search for the best driver in these locations, Select Search removable media, NEXT
- 7) Windows will find the driver on the CD and install the USB to Serial Adapter

Now Windows automatically detects the actual Com port, and you will install it in the same way as above

- 1) Windows will then display New Hardware Wizard
- 2) Tell it not to connect to the Internet this time to look for drivers, NEXT
- 3) Tell it to install from a list or a specific location, NEXT
- 4) Select Search for the best driver in these locations, Select Search removable media, NEXT
- 5) Windows will find the driver on the CD and install the USB Serial Port

You are now done.

VISTA installation screens will be slightly different AND you will want to make sure that you are NOT connected to the Internet when you are doing the installation

You can go to CONTROL PANEL, SYSTEM, HARDWARE, DEVICE MANAGER and look at the PORTS – you will see the USB to serial adapter listed as a COM port.